DART AEROSPACE LTD	Work Order:	24664
Description:	Part Number:	KINDOS
Dwg: (7) 424	04.	7
	Qty:	Page of

Step	Location	Procedure	Ву	Date	Qty
1	DC	Issue Fraveler	1		
			th,	0510-25	/_
	04	Inspect Kit for Bampletness AS		05.10.25	1
		per Attatched sheet			
2	PK	PACKAGE K10005 AS PEN	CZ.	5/11/07	1
		PPP K10005 Rev C, And place in stack			
35	AC	come with original batch number.			
23	AC		Suc	oslulzy	1
4	DC/0021	c/ose w/o:-	70	-\$11/2Y 05/11/88	/
					,
		÷			
				•	
	<u>·</u>				

Rev	Date	Change		
Kev	Date	Change	Revised By	Approved
				—

DART AER

DART AEROSPACE LTD	Work Order:	23076	
Description: Bearpaw Kit (13" x 16")	Part Number:	K10005	
Dwg: D2671 Rev. B1	Qty:	5 Kits	
Ref: K10005 Rev. A; DSK086-1 Rev. A		Page 1 of 1	

Step	Location	Procedure	Ву	Date	Qty
1	DC	Issue Traveler	11		_
		Note: (1) K10005 Kit consists of Qty (2) D2671	(PX)	05.04.19	5
<u></u>	50	Dwg not required	10		
2	DC	Photocopy bluefile: K10005			
		D206-559-021 NK 17 93- D500-572-021	anl	40100	_
		and create labels per PPP K10005 CHG002	M	05.04.27	フ
		(Bag Bluefiles separately)			
3	GA	Cut 2 blanks per (1) K10005 Kit			
		Cut blank: 13.25" x 16.00" x 1.00" thick (+0.030/-0:000) per			
		DSK086-1			
İ		Material: Black UHMW 1"	no	1 1	<i></i>
		(MUHMWB10) Batch: <u>B</u> 17726	112	0406/02	5
4	MV	Inspect material for defects or damage prior to machining	my	2/0//2	5
5	MV	Machine as per Folio and Dwg D2671 Pur (e)	1	12 00,100	<u> </u>
		Identify as D2671	Kn	05/16/03	5
6	QC2	Inspect parts as they come off the CNC machine	120 D	1 1	
		-	M	05/06/03	_5
7	MV	Deburr 50	And	odoilo3	5
8	QC8 & 5	Second inspection	21	05.06.04	5
9	KP	Pick: Packing Kit (Note: D2671 is on the BOM as material	7.7	03.06.04	
	, , ,	from step 3)			
		Qty Part Number Description Batch]	
]	4 D2182B050 Rubber Cushion <u>B2187</u> 2 •		ļ	ļ
		8 D2274 Radius Block <u> </u>			
		2 D2671 Bearpaw <u>523076</u>			
	\ \ \ \	74 D2438 Clamp <u>522503</u>			
	1	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
		8 AN4-17A Bolt 1914526			
1		16 AN960JD416 Washer m16941			1
		8 MS21042L4 Nut (or -4) 17/5924			
		2 QS200M44S Clamp V116020			
		1 Paperwork package from Step 2	CL	05/06/07	5
10	QC4	Inspect Kit for 100% Completeness on the W/O			
			SB	05/04/07	5
11	PK	Identify and pack for shipping as per PPP K10005 REO.C	CL	05/06/09	5
12	AC		1.0	1 /	
	<u> </u>	Cost / part	AS.	05/06/13	5
13	DC	Close W/O /60.50		66-111	ا ہے
		Inspect Level 21		0.06.14	2

Rev	Date	Change	Revised By	Approved
Α	99.12.17	K10005 created for Bearpaw Kit	EC	
В	03.05.28	Reformat; Incorporated D2671	KJ/RF	11
С	04.02.17	Blank size changed	KJ/JLM	de

\$ 106/10

DELEASEN

Job Costing Report

Dart Aerospace Lto Hawkesbury	d.	ι	dol	Costing R	epor c	Nov 24 02:54	1, 2005 pm
Work Order No Project Name Project For Work Order Type Main WO Number House Part Number Description: Manufactured: No Amount Req'd: Amount Done: Start Date Est Finish Date Act Finish Date Drawings Reqd Ok for Approval Approval Rec'd		0024664 K10005 Main RTN424 0 0 10-25-05 11-24-05 No			Department Burden Finonice invoice inv	<pre>lags : NNNNN s : Close State : Not I Date : Number : Amount : try No : in : 0.</pre>	ed Invoiced 0.00 0.00 0.00 000%
		Estimated		Actual	Var. %	Posted	To Post
Material Cost	:	0.00		0.00	0.00	0.00	0.00
Engineering Hours Engineering Cost	:	0.00		0.00	0.00 0.00	0.00	0.00
Production Hours	:	0.00		0.17	100.00		0 54
Production Cost Packaging Hours	:	0.00		2.51 0.00	100.00	0.00	2.51
Packaging Cost	:	0.00		0.00	0.00	0.00	0.00
OverHead Hours OverHead Cost	:	0.00		0.00	0.00	0.00	0.00
CNC Hours	:	0.00		0.00	0.00		
CNC Misc. Hours	:	0.00		0.00	0.00 0.00	0.00	0.00
Misc. Hours	:	0.00		0.00	0.00	0.00	0.00
Burden		0.00	==	0.00	0.00		
Darden	•	=======	==	======	======		
Total Cost	:	0.00		2.51	100.00		
Margin Selling Cost	:	0.000		0.000 2.51			

Actual

Estimated Actual Labour Hrs/Amount Done : 0.00 0.00 Profits/(Loss) : 0.00 (-2.51)